University of Windsor

Facility Services

# NOTICE OF SERVICE INTERRUPTION/WORK FORM

**Date of Request (yyyy/mm/dd):** 2025-09-13 **Requester**: Darrell Hennessy

**Start Date – End**

Start Date (yyyy/mm/dd) 2025-09-16 Time (s) 7:30 AM
End Date (yyyy/mm/dd) 2025-09-17 Time (s) 4:00 PM

Notes Air Handler HV-8 shut down for fan cabinet repair

**Building(s) Affected:**
**1:** Essex Hall EH **2:** Please Select
**3:** Please Sele **4:** Please Select

**Areas/Rooms Affected:** _____

**Service to be interrupted:**
**1:** _____ **2:** _____
**3:** _____ **4:** _____

**Description/Reason for Project:**

Air Handler HV-8 shut down for fan cabinet repair

**Contractor:** _____ **Phone #:** _____

**Contractor/Project Managers:** _____ **Phone #:** _____

Should you have any questions or concerns, please contact

Darrell Hennessy, Zone Supervisor
(519) 253-3000 ext. 2890
darrellh@uwindsor.ca

**Notes:**

The following reference links are attached for your information:
http://www.ccohs.ca/oshanswers/chemicals/asbestos/whatis.html
https://www.pinchin.com/services/hazardous-building-materials/133
http://www.pshsa.ca/wp-content/uploads/2014/05/Asbestos-in-the-Education-Workplace.pdf
http://www1.uwindsor.ca/facilityservices/AsbestosInventory